


Pelco spectra III master reset



Insert one end of the cable into the reset holes make sure the other ends do not short. Plug camera into the back box then short the ends together and release let the camera boot up. After boot up take the camera out of the back box and remove cable and plug the camera back into the back box and let boot up. Use as normal.